

McCLAIN

MACHINE TOOL SOLUTIONS


Zeman Technologies

Committed to 100% Customer Satisfaction

Call (314) 432-3220

Did You Know? Skip the Milling, Run Non-Conformed Stock!

Sometimes it makes sense to run hex or other stock rather than milling to shape. To set up the machine, use a round bar loader collet to fit over points of the stock. In Spindle 1, use a chucking sleeve with a pin to hold the collet in place as a new bar is loaded. To teach the machine rotational relationships, you will now perform phase adjustment.



You can adjust phase between the following on your Citizen:

- Main spindle and guide bushing
- Main spindle and back spindle
- Main spindle, guide bushing, and back spindle

In the phase adjustment menu, there are three (3) selections located on the right. Enter the desired number in the Operation Select field, close all doors, and press the menu key [Phase Adj] and Start Key simultaneously. A phase adjustment confirmation message will appear.

Operation Select Phse adj between m sp and GB

Select command item and
press [INPUT] key.

Pass the material through the spindle and
the guide bushing.
After that press menu key [Phse adj] and
START key simultaneously.

1. Phase adj. between
main spindle and
guide bushing
2. Phase adj. between
main spindle and
back spindle
3. Phase adj. between
main spindle GB,

Lastly, add M26 to bar loader sub program to line up guide bushing and main spindle at bar change.

O8000(**BAR-CHANGE-HEX**)

\$1

M9

M3S1=25M53

G0X#814+#815W-3.8

M54

M7

M55

M6

M3S1=#817

M26

G99G1W3.8F.01

M52

X#824F#822

M99

\$1 (**Pick Off-Cut Off Hex Part**)

T100

G50S4000

G0X.68Z1.3+.63T1

M97M95

M3S1=500M24S2=500

G814R0(**Change R to Shift Phase**)

M77

G96M3S230

G650

!L1

G1X.6F.003

G0X.68

W-.03

G1X.625

X.6W.03F.001

G231X-.1A-.02F.003

G97M5M25

G113


M96M94

For questions, check your machine manual or give us a call!

Miss our Last Tech Tips? Click Below!

Did You Know? Citizen ECO Screen and Monitor

Example graph displays



Equipped standard on Citizen lathes, the Eco Monitor shows machine power consumption in the form of a graph. The screen shows various power consumption data points. Working from the I/O screen, this data can be outputted (in CSV format) to a CF card or network.

Machine Operation Information

Did You Know? Cincom Low Frequency Vibration-Cutting




What is LEV?

Chip Control: Servo-controlled axes oscillate in the axial direction, and machining is carried out while synchronizing this vibration with spindle rotation. The air cutting time created during machining leads to intermittent chip removal.

LFV-Produced Chips: Two 14.3 gram samples of 304 Stainless, which would you prefer?

[View our Webinar on Low Frequency Vibration Here](#)



[Website](#)

[Products](#)

[News](#)

[Support](#)

[Contact Us](#)

